## ALUMINUM EXTRUSION FACTORY SOFTWARE GENERAL CATALOG

Constant speed extrusion (RcdWin) Isothermal extrusion (RcdWin) Extrusion management (EM) Extrusion data analysis (EDA) Extrusion Plant automation (EP)

RC Digital,Inc. http://www.rcdigital.co.jp 2019/10/28

# 目次

- 1. Five programs that improve the productivity of aluminum extrusion and help with maintenance and data analysis
- 2. System configuration
- 3. System configuration example (constant speed extrusion / isothermal extrusion)
- 4. Constant speed extrusion (RcdWin)-control screen
- 5. Constant speed extrusion (RcdWin)-Overshoot prevention
- 6. Constant speed extrusion (RcdWin)-Automation of rise adjustment (1)
- 7. Constant speed extrusion (RcdWin)-Automation of rise adjustment (2
- 9. Constant Speed Extrusion (RcdWin)-Pressure Limit and Inclined Extrsion
- 10. Constant speed extrusion (RcdWin) -Plc interface data
- 11. Extrusion data search (RcdWinMoni)
- 12. Extrusion management (EM)-various functions

- 12. Extrusion Management (EM)-Schedule function and database function
- 13. Extrusion Management (EM)-Billet length schedule simulation
- 14. Extrusion management (EM)-Aluminum extrusion profile defect detection
- 15. Extrusion data analysis (EDA)-Die selection and idle time graph
- 16. Extrusion data analysis (EDA)-Die usage history and extrusion billet table
- 17. Extrusion data analysis (EDA)-Extrusion billet list and extrusion data search
- 18. Extrusion data analysis (EDA)-Real-time monitoring and yield
- 19. Isothermal extrusion (RcdWin)-Extrusion parameters entered in EM
- 20. Isothermal extrusion (RcdWin)-Extrusion parameters entered in RcdWin
- 21. Isothermal extrusion (RcdWin)-Extrusion examples
- 22. Extrusion plant automation (EP)
- 23. Remote maintenance

### FIVE PROGRAMS THAT IMPROVE THE PRODUCTIVITY OF ALUMINUM EXTRUSION AND HELP WITH MAINTENANCE AND DATA ANALYSIS

Constant speed extrusion (RcdWin)	<ul> <li>This is a constant speed extrusion controller that automatically suppresses overshoot and speeds up startup for each die.</li> <li>It automatically adjusts the ram and torque relational expression, rise coefficient and constant velocity parameters.</li> </ul>
Extrusion management (EM)	<ul> <li>Register and search extrusion parameters such as extrusion speed in the database for each die.</li> <li>Extrusion can be performed according to the schedule for each die.</li> <li>The billet length schedule is calculated taking into account the length of the long billet and set on the machine.</li> <li>Al detects defects in extruded profiles.</li> </ul>
Extrusion data analysis (EDA)	<ul> <li>IT can be used in the extrusion process for each die.</li> <li>Extrusion data can be analyzed with extrusion forms and graphs for each die.</li> <li>You can calculate the yield per die.</li> </ul>
Isothermal extrusion (RcdWin)	• Controls the rise of temperature. A controller that performs isothermal extrusion with $\pm 1^{\circ}$ C error by adjusting parameters.
Extrusion Plant automation (EP)	<ul> <li>Real-time monitoring from long billets to cutting billets, cutting billets to extruded shapes, and extruded shapes to products.</li> <li>The parameters are retrieved from the database by die number or lot and set in the machine.</li> </ul>

# SYSTEM CONFIGURATION

- 1. This is an interface PLC that is connected to a personal computer via LAN.
  - 1. Three programs run on one computer.
  - 2. The PLC is for exchanging signal data with the equipment.
  - 3. There are two LAN ports for the PC, one for the PLC and the second for the Internet.
- 2. The PLC is for exchanging signal data with the equipment.
  - 1. An internet LAN is required.
  - 2. Access the factory system database.
  - 3. Remote maintenance is performed using the Internet.



# **SYSTEM CONFIGURATION EXAMPLE**(CONSTANT SPEED EXTRUSION / ISOTHERMAL EXTRUSION)

#### Constant speed extrusion

- Analog-in data requires main pressure, ram speed, (set ram speed) Note 1, puller speed, monitor torque, and manual volume.
- Digital-in is during extrusion, cycle stop (Wait), first billet extrusion prepare, die change, extrusion control used / not used.
- 3. Analog out is output control torque.
- 4. For Digital Out, a constant speed program is in operation.
- 2. Additional signals for isothermal extrusion
  - 1. Product outlet temperature, billet temperature, set billet temperature, output billet temperature.
- 3. The PLC network is a CC-Link IE field network.
- 4. Remote maintenance is performed using the Internet.

Note 1> When using extrusion management (EM), the set ram speed is not required.



### CONSTANT SPEED EXTRUSION (RCDWIN)-CONTROL SCREEN

#### 1. Graph line name

- 1. Light blue: Setting speed
- 2. White: Ram speed
- 3. Red: Pressure
- 4. Green: Puller speed
- 5. Blue: Monitor torque (torque signal actually output to the pump, oil flow rate in the pipe)
- 6. Yellow: Torque signal by RcdWin (white when steady)
- 7. 8V white: Pressure limit value



In about 5 seconds from the start, the ram speed becomes constant.

### NSTANT SPEED EXTRUSION (RCDWIN)-OVERSHOOT PREVENTION

- Overshoot prevention 1.
  - Predicts the rise of the ram speed by the torque and ram speed relational expression and prevents overshoot. 1.
  - With normal PID control, the amount of overshoot is large. 2.
- Productivity improvement 2.
  - The extrusion setting speed can be increased by preventing overshoot. Therefore, production increases. 1.
- Improved maintainability 3.
  - The ram and torque relational expression, start-up coefficient and constant speed parameters can be automated. 1.



Ram speed and torgue have a linear relationship.

Note> The term torque is used to mean the oil flow rate.



Relational equation between ram speed and steady torque

### CONSTANT SPEED EXTRUSION (RCDWIN)-AUTOMATION OF RISE ADJUSTMENT (1)

- 1. Automatic adjustment to suppress overshoot and shorten rise time.
  - 1. Even if the die changes, the rise is automatically adjusted.
  - 2. Automation parameters are rise factor and rise time.



Overshoot with a rise factor of 1.0.

Note> Rise factor: Ratio to set ram speed



The rise factor is now automatically 0.9. There is almost no overshoot.

### CONSTANT SPEED EXTRUSION (RCDWIN)-AUTOMATION OF RISE ADJUSTMENT (2)

- 1. Automatic adjustment to suppress overshoot and shorten rise time.
  - 1. Even if the die changes, the rise is automatically adjusted.
  - 2. Automation parameters are rise factor and rise time.



The rise factor is 1.0 and the rise time is 9 seconds or more.



The rise factor is automatically 1.1. It became constant speed by the rise time 9 seconds.

### CONSTANT SPEED EXTRUSION (RCDWIN)-PRESSURE LIMIT AND INCLINED EXTRSION



### CONSTANT SPEED EXTRUSION (RCDWIN) -PLC INTERFACE DATA

Pic Interface Data

- 🗆 🗙

#### Plc Interface Data

item number	Tag name	comment	5 pe	Plc No.	Pic device	Word count	Low resolution	High resolution	Low Volt	Hi
r 1'	D09~15	DI	AI	PLC1	D100	12	0	4800	0	
2	D016-31	D1002		PLC1	D101	0	0	1	0	
3	Billet Length	Al Billet L		PLC1	D102	0	0	1	0	
4	Profile Temperat.	ALP. T		PLC 1	D103	0	350	600	Ũ	
5	Pressure	AI Pressure		PLC-1	D104	0	8	250	0	
6	Torque(Flow rate)	AI Torque		PLO1	D 105	0	0	4000	0	
7	Ram Speed	AI Ram		PLC1	D106	0	0	38800	Ű	
1	Puller Speed	AI Puller		PLO1	D107	0	B	1000	0	
9	Billet Temperatu.,	ALB. T.		PLC1	D188	0	950	680	0	
10	Setting Billet Te	ALR. B.T.		PLC1	D109	0	350	500	0	
11	Setting Ram Spe.	AI R.R.		PLC1	D118	0	B	300	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	
12	Setting Volume	1		PLC1	D111	0	0	100	0	
13	Ao Torque1	Torque	AO	PLC1	D0126	3	0	4000	0	
14	Ao Settine Billet.	R. B. T.		PLC1	D0127	0	8	1	0	
15	Ao Average ram _	R. ERROR		PLC1	D0128	0	8	1	0	
16	DO0-15	PC ON	AO	PLC1	D8125	- 1	0	1	0	

#### Plc data

1. Set the Plc type, IP address, port, and protocol.

#### 1. Plc interface data

- 1. Set the Plc device, measurement data, output data scale, etc.
- 2. Maintenance is better.
- 3. Data type AI Plc device numbers must be consecutive.
- 4. DI is also imported as AI.
- 5. DO is also output as AO.

Plc

#### Plc Data

	Item Number	Pic Number	Plc Type	Plc Host	Pic Port	Plc Protocol
k	+	PLO1	MELSECQ_Q03	192.168.12.2	2000	UDP

Cancel

OK

### **EXTRUSION DATA SEARCH (RCDWINMONI)**

#### 1. Extrusion data search

- 1. The latest 20,000 extrusion data can be searched by date and displayed as a graph.
- 2. Display data can be output as a CSV file.
- 3. Data has a sampling time of 0.1 seconds or less. Data is also logged in extrusion data analysis (EDA). However, EDA sampling time is 1 second.



#### 1. Application of CSV file

- 1. The figure on the right is a ram speed spectrum analysis.
- 2. The ram speed is vibrating due to friction. Amplitude 0.03  $\pm$  0.015 [V] 0.09  $\pm$  0.045 [mm / s] Period about 0.3 seconds
- 3. If done regularly, it will help maintain the machine.



20

### **EXTRUSION MANAGEMENT (EM)**-various functions

#### Extrusion management (EM) functions

- 1. You can register, change, and search for each die of constant speed extrusion and isothermal extrusion parameters.
- 2. Constant speed extrusion and isothermal extrusion parameters can be set in the machine.
- 3. You can create an extrusion schedule for each die
- 4. You can get the extrusion schedule from the factory system database.
- 5. Even if the extrusion speed is the product speed [m / min], it can be used as it is (converted to the ram speed [mm / s] by the extrusion ratio).
- 6. Billet length schedule simulation is possible.
- 7. Can detect aluminum extrusion profile defects.

A 2007-87 (2757) PARAMETER Constrained of the second seco	Apple 1980         OKI         Spät (Protect           Proces 746 /3         Spät (Protect         Spät (Protect           Sp7 /2 - A         Magnet (r, 4, 40) - (44, 40)         Spät (Protect           Sp7 /2 - A         Magnet (r, 4, 40) - (44, 40)         Spät (Protect           Sp7 /2 - A         Magnet (r, 4, 40) - (44, 40)         Spät (Protect           Sp7 /2 - A         Magnet (r, 4, 40) - (44, 40)         Spät (Protect           Sp7 /2 - A         Magnet (r, 4, 40) - (44, 40)         Spät (Protect           Sp7 /2 - A         Magnet (r, 4, 40) - (44, 40)         Spät (Protect           Sp7 /2 - A         Magnet (r, 4, 40) - (44, 40)         Spät (Protect           Sp7 /2 - A         Magnet (r, 4, 40) - (44, 40)         Spät (Protect           Sp7 /2 - A         Magnet (r, 4, 40) - (44, 40)         Spät (Protect           Sp7 /2 - A         Magnet (r, 4, 40) - (44, 40)         Spät (Protect           Sp7 /2 - A         Magnet (r, 4, 40) - (44, 40)         Spät (Protect           Sp7 /2 - A         Magnet (r, 4, 40) - (44, 40)         Spät (Protect           Sp7 /2 - A         Magnet (r, 4, 40) - (44, 40)         Spät (Protect           Sp7 /2 - A         Spät (Protect         Spät (Protect         Spät (Protect	20120218 75.76
Image: Second	0         0.1 (0.00) <th>1980次16 </th>	1980次16 

- 1. Constant speed extrusion (RcdWin) and extrusion management (EM)
  - 1. The extrusion parameters are set with EM, and constant speed extrusion is executed with RcdWin.
  - 2. RcdWin can run without EM. However, productivity will be improved if the extrusion schedule can be entered and extrusion parameters can be searched from the database.

### **EXTRUSION MANAGEMENT (EM)-SCHEDULE FUNCTION AND DATABASE** FUNCTION

1.

- Schedule function 1.
  - The extrusion schedule can be obtained for three 1. days from the factory system database.
  - Ten extrusion dies can be entered manually. 2.
  - Any of the 10 extrusion dies can be selected. 3.
  - Click [Number  $1 \sim 10$ ] to move the extrusion die 4. number to [Inquiry Extrusion Die].
  - [11 Number] can select the extrusion die number 5. from all schedules.

- Database function
- Click [Search] to set the extrusion parameters from the 1. database.
- The extrusion die number moves to [Extrusion Dies under 2. Control].
- Click [Register Database] to set the extrusion parameters in 3. the database.



Click Set to Machine to set the extrusion parameters to the machine

### EXTRUSION MANAGEMENT (EM)-BILLET LENGTH SCHEDULE SIMULATION

1.

1.

2.

#### 1. Characteristic

👻 Extrusion Management RCDIGITAL

- 1. Billet length schedule simulation program that can be used conveniently at the extrusion work site.
- 2. Billet length schedule can be set in the machine.
- 3. Long billet length can be considered.
- 4. Changes in profile extrusion length (product unit weight changes due to heat) can be taken into account.

#### Five schedule functions

- Considering the long billet length, keep the billet length constant.
- Simulate billet cutting plan so that there is no remaining long billet.
- 3. A mode that does not consider long billets. Specify the first billet length.
- 4. A mode that does not consider long billets. The first billet length is calculated by the distance between platens.

5. A mode that does not consider long billets. Calculate without specifying the first billet length.

Dre	an Nia + 2			Bill	atlena	th sch	dulo cimula	tion	2013/03/03	17.52
Fre	SS IND . 3			Dille	stieng	ui sone	suule sillula	luon		
Orde quar 202	er htity C	Order length [m] 5.0	Product . [kg/1	ctUnitW n]	Billett ht [kg,	InitWeig (m]	ButtThicknes s [mm] 5		2 2	alculated roducts 02
Num hole 2	berof s□	ExtrusionTa eL. [m] 45.0	bl Plater distan 1.5	ce [m]	Cuttin mp.L.	gConsu [mm] 「	Extra length [m] 1.5			
1stk leng 400	pillet th[mm] ┌	● OFF ● C Billetlen	ngthCalcu	lation	LongB gth[m 6500	illetLen m]	Ext.DieCross Sec.[mm2] 221			
Long Valu	gBilletLIni ue[mm]	C Platen di	stance [m]		BilletL in.[mm	engthM	Maximum billet length	SplitMinimur L. [mm]	m Measu.Extru sionL.[m]	Measu.Extru sion ratio
400	I <b>v</b>	LongBilletL	Consider	ation	280		650	100	44.0	44.3
		○ OFF ○ ON Fixed	l billet len	gth	Extrus thMin.	ionLeng [m]	NoCalc.Produ	ctNum.Error	Measu.Prod. U.W. [kg/m]	DrawingUnit W. [kg/m]
Cal	culation res	C ON No lo	ng billet le	ft	20.0		CON		0.494	0.60
	Long billet no	1-1	2-1	2-2		2-3	3-1	3-2	-OneProd.Bill etLen.[mm]	
•	Billet lentgh[mt	m] 400	165	565		104	461	565	44	
	Number of bill.	1	1	11		1	1	4	Delev	
	Extrusion lengt	t 22.2	31.5	31.5		5.6	31.5	31.5	Calcu	lation
	Long billet rem	i 0	6335	104		0	6039	3509	exec	ution
	Number of pro.	8	2	12		2	10	12	Set par	ameters
	Total number	8	2	132		2	10	48	-	

Billet length schedule that keeps billet length constant considering long billet.

#### velocity extr schedule si

### EXTRUSION MANAGEMENT (EM)-ALUMINUM EXTRUSION PROFILE DEFECT DETECTION



### EXTRUSION DATA ANALYSIS (EDA)-DIE SELECTION AND IDLE TIME GRAPH

1.

1

8.

#### 1. Characteristic

〒 押出データ解析-RCDIGITAL VER. 2018.05.21

- 1. The aluminum extrusion factory can be converted to IT.
- 2. Various functions are realized using the data stored in the database by the constant velocity extrusion, isothermal extrusion program (RcdWin), and extrusion management (EM).

#### Various functions

- Graphing of form data.
- 2. Detection of equipment abnormal data
- 3. Non-extrusion time (idle time) graph, short stop time, die change time CSV.
- 4. History of extrusion parameters per die (extrusion speed is particularly important).
- 5. Extrusion die usage history.
- 6. Extruded billet table
- 7. Real-time monitor.
  - Yield

Star	t 2017#06	月17日(土曜日)00時* 💌	End	2017年06月18	8(日曜日)12時* 」	・ ダイス雪	2番 例>387	10		根本			
	開始時間	学们又型番	ダイス 精業	ラム速度設定 [%]	ラム連度設定 最大1%1	ホール数	EL-HELS	型材质面積	神出社	-	1.	Non-e	ext
£1.	2017/06/17 7	1001	1	46	46	1	False	1038.0	25.3			1.	-
	2017/08/17.7	2019.04	1	40	40	1	False	450.0	58.4			2.	
	2017/06/17 6	25712	4	52	52	1	False	1355.0	19.4				
	2017/06/17 5	27941	1	36	36	1	False	879.0	29.9				
	2017/06/17 5	84229	2	59	59	1	True	1141.0	23.0			_	
	2017/06/17 5	48779	3	36	36	1	False	978.0	26.9		30以上		
	2017/06/17 3	48548	12	50	50	1	False	435.0	60.4				
	2017/06/17 3	5238	6	50	50	1	False	700.0	37.6		29-303	_	
	2017/06/17 3	1678	10	48	48	1	False	475.0	55.3		28-295		
	2017/06/17 2	299.0	7	46	46	1	True	515.0	51.0		27-285	1	
	2017/06/17 2	23818	2	29	32	2	True	131.4	100.0			-	
	2017/06/17 2	383.67	1	25	25	2	False	91.7	143.3		26-275		
	2017/06/17 1	299527	6	31	31	2	False	133.0	98.8	17.1	25-26S		
	2017/06/17.0			28	21	2	Eslas	132.0	00.0	*	24-255		
117	選択表	8093							イス交換時間Crv	- 1	23-24S		
主15	ゲイス型名を入力	りした場合は、「検索でゲ	(ス使用)	夏度に移動します					チョコ停にコッファイル		22-235		
								1	非押出時間X1x27	017-0	21-225		
	o Minas		nub ce a						1	18.7	20-215		
34	人通訊教	9/4 AB/HIGUE	A PORT						1	#0.5	19-20S		

• Transit to [Extrusion Die Usage History] screen.

#### Non-extrusion time XIsx file

Click the [Non-extrusion time XIsx file] button.

The idle time of the Start and End periods is output to the Xlsx file as a graph.  $_{\rm o}$ 



### EXTRUSION DATA ANALYSIS (EDA)-DIE USAGE HISTORY AND EXTRUSION BILLET TABLE

#### 1. Usage history of extrusion dies

- 1. The usage history of the same extrusion die is displayed in order from the newest.
- 2. The extrusion parameters of the extrusion die on the selected day are displayed in the table below.
- 3. The extrusion manager can examine the parameter transitions.
- 4. You can ask the operator why the parameter was changed. In particular, changes in extrusion speed are important because they directly affect productivity.
- 5. When [Extruded Billet Table] is executed, the screen switches to the extrusion form printing screen of the extrusion die on the selected day.

#### 1. Extruded billet table

- 1. By executing the [Print] button, you can print forms on a printer, Excel, PDF, or Word.
- 2. Extrusion can be seen in a graph by executing the [Graph] button.
- 3. You can set abnormal values for measurement data in the table below. The top is above, the bottom is below. Abnormal values are preceded by \*\* before the numerical value in the form.

H	押出データ解析-RC	DIGITAL VER. 20	118.05.21								100												
										2018/12	2/03 18:39	)											
ŧ	甲出機:1					ダイス	使用履	歷				<u>田</u> 博:	出デ-91	解析-RCDIGIT	AL VER. 2018.	.05.21							u x
												锢	出機	• 1				押出ビレッ	ト表		2018/12	2/03 19:35	
	開始合命行動	ダイス型番	ダイス枝	ラム連想	tikit 5	ム連度設定	モレット合計	ダイス予熱炉 1	ダイス予熱炉	ダイス予熱炉 3	木一ル鼓												
¥.	2017/06/17 3	anse:	12	1.54	50	50.0	57	496	588	492	1							日付 2017	/06/17 🕅	始時間	03:33:43 🙀	了時間	05:05:2
	2017/06/15 1	and the second	19	1 8	36	36.0	1	587	586	519	1	21	ス型	蕃 48546	6 - 12	タイス予熱炉1	1 496°C	タイス・	予熱炉2 588	°C	タイス予察	奶 <b>₽3 492°</b> ℃	0000088
	2017/06/14 6	1050	19	1 3	36	36.0	61	586	586	452	1	赤-	-1	1		型材断面積	÷	435.0mm2			及-	(ス交換時間	a]1 152
	2017/06/10 4	1956	13	1 3	34	34.0	114	377	505	432	1	押出	出機	N. 1		1.19 19 19	81#	無 押出	比	60.4	1 员-	ィス交換時間	間2 152
	2017/06/08 5	1956	19	1	36	36.0	114	586	587	454	1					1	Service and	1		1			-
	2017/06/06 2	1000	12		40	40.0	116	586	580	534	1		1 <b>1</b> 15	ビビレット数	/551厚	ビレット長	ビレット温度設定	ビレット温度	押出型材出	終了温度	最高温度	メイン圧力	
·] 通:	たのパラメータ	8		2	2			5	<u> </u>		1.0		N		[mm]	[mm]	ra	[P]	*C[1089]	.clao@1	°C	[bar]	-
100	2011321 P.													_		650	400	460	101.1	405.2	407.9	1420	
	PlankNo	設定製品温	設定製	50.08	放定といれ温	7 14		1-(EER	製品速度	ラム速度設定	ラム速度設定	-	2		14	658	480	460	501 5	500.9	504.0	156.0	-3
	Comino	度High	<b>度</b> Low		度			LIVER	[m/min]	[36]	[mm/s]		3		14	661	480	460	505.0	503.0	506.3	156.0	12
۲	3.	545	1	35	480	1	10	0.9	25	38	6		4		14	663	480	460	503.8	503.9	507.6	156.0	
-	2	545		35	480		10	0.9	25	42	6		5		14	663	480	460	504.9	504.2	508.1	156.0	
÷	3	545		35	480		10	0.9	25	46	6		6		14	660	480	460	508,1	505.8	510.6	154.0	57
_	4	545		035	480		10	0.9	25	48	6	-	7		14	652	480	460	506.1	584.7	508.4	155.0	- 24
•		0.0	N 23	13	100		82 - S	0.00	C 1965 (J		o (k)		0		19.4	887	400	Lann	E07 0	Ena S	Eno 9	1EE O	1
												異羽	「値の話	設定 上段:	以上 下段:	:以下						<u>2</u>	*
													Kat	卑	ビレット長	ピレット温度設定	ビレット温度	型材稳定温度	神出型林出口温	林了温度	最高温度	メイン圧力	-
82	1 20-10 30	105.40		30	10/1/11/11	ui.	10						No.	50	1000	500	500	550	550	550	550	200	
21.	A MERCEA	40340	and the second	10	DOM AND	ur	16						10 ×	3	300	400	400	400	400	400	400	0	
1	22(事用實明	19 M Kitoba										1.							1			_	. H
1	A PAGE ATTACK	THUS POLY	<u> </u>									417	(資格)	36.385 <del>J</del>		灌根ガイ2]	枯槁	12 PL	小合計	57			
-														10010		200 m				31		_	
												1913	HE Lot	*	EDDI	ガラフ							更る

# EXTRUSION DATA ANALYSIS (EDA)-EXTRUSION BILLET LIST AND EXTRUSION DATA SEARCH

- 1. Extruded billet list
  - 1. Information for each extrusion die: die number, die crosssectional area, etc.
  - 2. Information for each billet: Setting ram speed, ram speed, puller speed, main pressure, Max main pressure, Max main pressure duration, etc.
  - 3. The number of items displayed varies depending on the factory. The Excel form is about 3 pages in A4 landscape.



### EXTRUSION DATA ANALYSIS (EDA)-REAL-TIME MONITORING AND YIELD

Yield

Referring to the number of non-defective

products for each lot of extrusion dies, the

1.

1.

- Real-time monitor 1.
  - Extrusion status can be viewed in real time graph. 1.
  - Information for each extrusion die: die number, die cross-2. sectional area, etc.
  - Information for each billet: Setting ram speed, ram speed, puller 3. speed, pressure, etc.



Note> Displayed contents vary depending on the factory.

#### Note> Yield is optional.

EDE

15.23 [Ton] 13.71 [Ton]

90.045 [%]

91.369 [%]

ビレット記憶量

PL6563 M ML

歩留まり

收益率(建論値)

検索 \$8

\*

.

t

23

Yes

Yes

Yes

Yes

No

No

No

No

No

No +

合格

率(理

LA(B)

74.2

77.A

70.3

85.5

0.0

0.0

0.0

0.0

0.0

0.0

## ISOTHERMAL EXTRUSION (RCDWIN)-EXTRUSION PARAMETERS ENTERED

. IM Elsothermal extrusion features

- lsothermal control with an error of + -1° C is possible by adjusting parameters.
- Automatic adjustment of isothermal start-up by the start-up factor with proven results in constant speed extrusion.
- 3. Automatic adjustment of billet temperature (billet taper temperature).
- 4. By monitoring the upper limit extrusion speed, there is no danger of runaway extrusion speed.
- 5. Database of isothermal extrusion parameters by extrusion management program (EM).
- 6. Automatic adjustment of emissivity by extrusion management program (EM).

Emissivity is set automatically with a radiation thermometer of the type that sets the emissivity. Parameters are maximum emissivity, minimum emissivity, measured product temperature (value measured with contact thermometer)



Set product temperature: Enter the outlet temperature low and outlet temperature high. Set extrusion speed: The extrusion speed is monitored even during isothermal extrusion. Set billet temperature: A manual / automatic switch is required on the billet heater side. Green input box: [Current emissivity] and [Automatic billet temperature] are displayed by the program. It cannot be entered.

### Start Calc Stop Calc Temperature and Emissivity History 350 -- 0.3 450 -- 0.2 500 -- 0.15 535 -- 0.125 Calculation complete RS232C Reset End

Х

### **ISOTHERMAL EXTRUSION (RCDWIN)**-EXTRUSION PARAMETERS ENTERED IN RCDWIN

🝸 Isothermal

Isothermal extrusion parameter screen: Click [Isothermal extrusion] on the RcdWin menu bar.

Extrusion setting	525	Ex>540[°C]	Setting Ram Speed	🔡 RcdWinMoni	理出機速度制御コントローラ・ログデータモニター) - RCDIGITAL	
Allowable temperature + side	25	例>+3[℃]	Ram Speed allowable error	終了 圧力制限 V.2018/05/30W Difk c w si	等温押出 傾斜 関係式 立上時間 制御方法 PID ラムコンロールディスフ DOfmushing pol	A RCDIGITAL
Allowable temperature- side	-25	Ex≻-3[°C]	Time from start before Isothermal control begin	設定速度	, ·,	
Wating time	3.5	Ex>3.5[Sec.]	Torque up is disabled at the start for a certain ti	25-速度 押出機	    	出力トルク
Control time	1	Ex.>1.0[Sec.]	Error Delta Temperature to start Isothermal	10		
Torque slope	-0.0005	Ex> -0.0005[V]	Error Delta Temperature	2	Ex.>2[Sec.]	
Torque slope Start	5	Ex> 20[Sec.]	continue time OFF	1. Isothe	ermal extrusion parameters [Wait time]: Enter the wait time for feedback contro	Ι.
Use SpeedUpCo		FeedForward 0	Ex> 0[V]	2.	[Control time]: Enter the control time for feedback of	ontrol.
O OFF		0 means to use Relational equ	ation	3.	[Torque slope]: Decreases the torque by a certain a	mount of "V".
• ON		Percentage of 1.1 premiums in Relational Eq.	Ex.>1.1[-]	4.	[Torque slop start time]: Start time of [Torque slope	].
Auto SpeedUpCo		Max SpeedUpCo 2	Ex> 2.0[-]	Allowable	I.0 Ex.>1.0[V]	
ି OFF ଙ ON		If the profile does not reach th SpeedUpTime, SpeedupCo is a	e set temperature within djusted.	5.	[Use rise coefficient]: Select whether to use the rise isothermal start-up. When ON: The isothermal start- the start-up factor and start-up time. When OFF: Iso controlled with a constant torque [feed forward torc	coefficient in up is controlled by thermal start-up is jue].
Setting Billet Temperature	480	Ex> 480[°C]	Billet Temperature allowable error	10£	[Feed for wang for que]: When [Rise coefficient use] is start-up is controlled with a constant torque. However, it is controlled by the value of the relational equations of the relation equations of the relations of the r	s OFF, isothermal 'er, if the value is 0,
Temperature © OFF					Other parameters are omitted.	
C ON Note> Green input box: \	Value entere	Parameters co	o <b>nfigurable in EM</b> gement	ОК	Cancel	

program (EM).

### **ISOTHERMAL EXTRUSION (RCDWIN)** -EXTRUSION EXAMPLES

RedWinMoni (学生     End Presser Limit     V.2017/11/22 K     DI [seti] jágzses]p k     (ジテ注意     プラー注意     アメル     PodeZava     10     5	##温度制器D2HD-5+07デーPECター〉 - RCDG(AL bothermal Relational Equation Rise Time Control Method PED Rom Control D's pEd/4年48.05884 Bjoede w s] 000000001 DO(100月 11 2.0mm/s うん注放 4.9mm/s 5.4 5.4m/sminn 2.4v 出力) 2.2 #58245434360.0	CDHM1854) - 95kg/cm22 温度 522℃ - 95kg/cm22 温度 522℃ - 10 0v 12 小 温度 350v - 10 10 21 小 温度 363℃	Start바페: 2017/12/15 160815 0/11			
の の の の の の の の の の の の の	25 ]= 1.7   头 建度 (定常 Xmm/sec.]= 8.8 ]= 170.9   說定速度   [mm/sec.]= 2.0 525.0   說定速度   [%]= 6.7 541.0   終 速度  [mm/sec.]= 2.0	50 赤リューム(定常)[%]=18.9 A, B = 1.30 1.00 ^A, *B = 0.00 0.00 押出時間 [soc]=117.8	75	1. 100	When isothermal extrusion is OFF 1. The product temperature has risen from about 13 seconds.	1
1. Who	en isothermal extrusion		-9429-) - RCDORAL Son Control Displicitie Autocrisia Specializado DO[ton]] 1	ik tinj	Starl時間: 2017/12/15 16:24:48 10/13	
1.	Set temperature 525 °C ± 5 °C.	設定建度 2.0mm/s 74; フラー 速度 8.2m/minn 1945-054-02:2 mtdix154(34970) 10	出度 6.1mm/s 作力 1.9v 出力トルク 0	91kg/cm22 温度550℃ 0.0v という温度350v 設定という温度369℃		
2.	In order to raise the product temperature, the ram speed is overshooted by the rise factor for the first 10 seconds.	5				
3.	The ram speed is ramped down to prevent temperature rise.		25 A 建度 (宇家)(mm/soc]- 8 1 定達度 [mm/soc]- 2 0 設定達度 [%]= 6.7 本 逆度 [mm/soc]= 2 0 日土曜日1000	50 木リューム(定常)[%]=18.9 A.8 -1.301.00 *A.*8 -0.00.00 将出時間 [sec]=94.6 次の評出チータ 織道	75	100

# EXTRUSION PLANT AUTOMATION (EP)

- 1. Real-time monitoring from long billets to cutting billets, cutting billets to extruded shapes, and extruded shapes to products.
- 2. Acquire data from the extrusion parameter database and set it in each machine.
- 3. Link data with extrusion data analysis program (EDA).
- 4. Different die shapes can be monitored in the extrusion process, stretch process and profile cutting process.

Extrusion Plant Monitor Controller

No.	Lot No.	Billet No.	Profile No.	Die Message	Billet Cut	Uillet Taper	8 Aet Containes	Extrusion	Bun Out Table1	Shetcher	Film Dut Table2	Profile Culter	Culling- Table
661	160415-024	15		1		1							
660	160415-024 1	14					1						1
659	160415-024 1	13	28								2		
658	160415-024 -1.	12	24								2		
657	160415-024 1	11	22						1		2		
656	160415-024 1	10	20								2		
655	160415-024 1	9	18								2		1 3
654	160415-024		16						1		2		
653	160415-024 1	7	14								2		1
652	160415-024 1	6	12								2		
651	160415-024	5	10								2		1.3
650	160415-024 1	4	8								2		
649	160415-024 1.	3	6								2		1 3
F48	160415-024	2	4		-						.9		

# **REMOTE MAINTENANCE**

- 1. There are three maintenance methods: remote support, remote conference, and continuous monitoring. Remote monitoring software TeamViewer Host.exe can be installed for continuous monitoring.
- 2. Log in to a constant speed extrusion PC when you request an extrusion survey and investigate the extrusion data. Data is logged on the constantspeed extrusion PC so that past extrusion conditions can be reproduced.
- 3. When investigating, it is necessary to connect the local network to the Internet network. This is done by plugging the internet LAN cable into the hub for the local network.
- 4. Remote maintenance is performed not only in Japan but also in factories in Korea and China.
- 5. TeamViewer can automatically detect firewalls and proxy settings for remote monitoring. Communication is encrypted.

